



| Orig Tree Position         | Site        | Original Tree Species | Confirm Reason For Removal | 6 D's    | Planting Notes                                                                                                                                                  | Original Tree Easting | Original Tree Northing | Replant Species             | Replant Easting | Replant Northing |
|----------------------------|-------------|-----------------------|----------------------------|----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|------------------------|-----------------------------|-----------------|------------------|
| o/s 1 (2nd tree on street) | MILTON ROAD | Acer pseudoplatanus   | Damage to Surface          | Damaging | TR: Replanting, Sorbus aucuparia cultivar - Plant in new 800mm pit OPPOSITE 4 (same as felled tree)                                                             | 434541.19             | 385253.44              | Sorbus aucuparia 'Cardinal' | 434540.96       | 385253.4         |
| OPPOSITE 10                | MILTON ROAD | Acer pseudoplatanus   | Damage to Surface          | Damaging | TR: Replanting, Sorbus aucuparia cultivar - Plant in new 800mm pit OPPOSITE 10 (same as felled tree)                                                            | 434528.48             | 385239.37              | Sorbus aucuparia 'Cardinal' | 434528.33       | 385239.33        |
| o/s 27                     | MILTON ROAD | Sorbus intermedia     | Damage to Surface          | Damaging | TR: Replanting, Platanus x hispanica - Plant in new 800mm pit centrally o/s 23 CRESCENT RD (CHANGE IN TREE NUMBERS ON THIS RSL, specific SCC approval required) | 434516.19             | 385225.82              | Platanus X hispanica        | 434560.47       | 385280.7         |